



**Dominion**

# DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: MARCH 8, 2016

WEATHER: 63, A FEW CLOUDS

INSPECTED BY: K. ACRE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1307 → SAND BAGS + RIPRAP IN PLACE, AND NO STANDING WATER AGAINST SAND BAGS.
Erosion	N	N	SEVERAL SAND BAGS ARE RIPPED.
Low Point, B dike*			
Flow	N	N	1312 → SAND BAGS ARE IN PLACE AND THERE IS <del>NO</del> NO STANDING WATER AGAINST SAND BAGS.
Erosion	N	N	
Outfall			
water surface El. (top of stoplogs to water)			1318 → NO FLOW THROUGH WEIR, NO STANDING WATER AGAINST WEIR, AND WEIR APPEARS TO BE DRY.

\* See figure below.

**Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.):** → STANDING WATER AT TOP OF EMBANKMENT TO PONDS A, B, C. AS NOTED IN FIGURE BELOW.

(1318) → LOW POINT, C DIKE → NO FLOW OR EROSION, NO STANDING WATER AGAINST SAND BAGS, SAND BAGS ARE IN PLACE, AND SEVERAL SAND BAGS ARE RIPPED.  
→ STANDING WATER AGAINST AT INSIDE TOE OF EMBANKMENT TO POND C, SOME STANDING WATER AT INSIDE TOE TO EMBANKMENT FOR PONDS A & B, AS WELL.

